




1.11 ПЕРЕХОДЫ КРЕСТООБРАЗНЫЕ

Переход крестообразный плавный ПХп



Код исполнения		Артикул	Вес, кг/шт.	Размер, мм					Упак., шт.
Сендзимир	Окрашенные			A1	A2	L	L1	H	
034715	234715	ПХп 100x50x50	0,67	100	50	400	350	50	2
034725	234725	ПХп 200x50x50	0,86	200	50	500	350	50	2
034735	234735	ПХп 300x50x50	1,05	300	50	600	350	50	2
034745	234745	ПХп 400x50x50	1,25	400	50	700	350	50	2
034721	234721	ПХп 200x100x50	1,00	200	100	500	400	50	2
034731	234731	ПХп 300x100x50	1,22	300	100	600	400	50	2
034741	234741	ПХп 400x100x50	1,44	400	100	700	400	50	2
034732	234732	ПХп 300x200x50	1,55	300	200	600	500	50	2
034742	234742	ПХп 400x200x50	1,82	400	200	700	500	50	2
034743	234743	ПХп 400x300x50	2,21	400	300	700	600	50	2
034821	234821	ПХп 200x100x80	1,20	200	100	500	400	80	2
034831	234831	ПХп 300x100x80	1,46	300	100	600	400	80	2
034841	234841	ПХп 400x100x80	1,73	400	100	700	400	80	2
034832	234832	ПХп 300x200x80	1,86	300	200	600	500	80	2
034842	234842	ПХп 400x200x80	2,18	400	200	700	500	80	2
034843	234843	ПХп 400x300x80	2,65	400	300	700	600	80	2
034921	234921	ПХп 200x100x100	1,33	200	100	500	400	100	2
034931	234931	ПХп 300x100x100	1,62	300	100	600	400	100	2
034941	234941	ПХп 400x100x100	1,92	400	100	700	400	100	2
034932	234932	ПХп 300x200x100	2,06	300	200	600	500	100	2
034942	234942	ПХп 400x200x100	2,42	400	200	700	500	100	2
034943	234943	ПХп 400x300x100	2,94	400	300	700	600	100	2
021515	221515	КПХп 100x50	0,33	100	50	400	350	-	2
021525	221525	КПХп 200x50	0,53	200	50	500	350	-	2
021535	221535	КПХп 300x50	0,72	300	50	600	350	-	2
021545	221545	КПХп 400x50	0,91	400	50	700	350	-	2
021521	221521	КПХп 200x100	0,66	200	100	500	400	-	2
021531	221531	КПХп 300x100	0,89	300	100	600	400	-	2
021541	221541	КПХп 400x100	1,11	400	100	700	400	-	2
021532	221532	КПХп 300x200	1,22	300	200	600	500	-	2
021542	221542	КПХп 400x200	1,49	400	200	700	500	-	2
021543	221543	КПХп 400x300	1,88	400	300	700	600	-	2

